



PRSR STD
U.S. POSTAGE
PAID
PERMIT NO. 1347
OMAHA, NE

20-point inspection

- 1 Check thermostat
- 2 Check circulating motor
- 3 Check circulating blower blades
- 4 Check and flush condensate drains
- 5 Check motor belts
- 6 Check motor bearings
- 7 Lubricate blower motor
- 8 Check air filters
- 9 Check and tighten power connections
- 10 Check evaporator temp differential
- 11 Check condensor coil
- 12 Check refrigerant levels
- 13 Check condensor motor
- 14 Check condensor fan blade
- 15 Check all electrical connections
- 16 Check contactor
- 17 Check compressor amps
- 18 Lubricate condensor motor
- 19 Visual inspection of refrigerant piping
- 20 Inspect or replace system caps