



PRSR STD  
U.S. POSTAGE  
PAID  
PERMIT NO. 1347  
OMAHA, NE

## 20-point inspection

- 1 Check thermostat
- 2 Check operation of safety limit controls
- 3 Lubricate pump, fan, and motor bearings
- 4 Check and clean motor and blower assembly if needed
- 5 Check gas pressure on furnace
- 6 Check operation of inducer blower
- 7 Check burners and visually set for proper combustion & ignition
- 8 Inspect venting system
- 9 Check pilot, ignition system, and gas pilot safety system
- 10 Visual check of gas piping to furnace
- 11 Check pressure switch and power vent system
- 12 Check air filters and instruct customers on filter maintenance
- 13 Perform carbon monoxide test
- 14 Inspect combustion/ventilation air space
- 15 Inspect heat exchanger
- 16 Check condition of condensate line and flush
- 17 Inspect flame sensor
- 18 Check temperature rise
- 19 Adjust dampers
- 20 Turn on humidifier and check pad

